



NFPA 705 "FIELD TEST"



PASS


- FABRIC SELF EXTINGUISHES W/IN 2 SECONDS AT REMOVAL OF FLAME.




- MOLTEN DRIPS ONTO DRY SURFACE SELF EXTINGUISH W/IN 2 SEC

FAIL

- FABRIC CONTINUES TO BURN FOR MORE THAN 2 SECONDS AFTER REMOVAL OF FLAME



- MOLTEN DRIPS ONTO DRY SURFACE CONTINUE TO BURN FOR MORE THAN 2 SECONDS AFTER REMOVAL OF FLAME



THIS PAPER UNTREATED

THIS PAPER FR-TREATED

[nfpa 705 standard](http://nfpa.org) www.nfpa.org

- CLICK "STANDARDS"
- CLICK: 700-799
- CLICK: 705

[Fabric Burn Examples](http://www.3dxFlameCoat.com) www.3dxFlameCoat.com

- CLICK "BURN NOT VIDEOS"